



AVX Corporation

CP0805B1890AWTR

Part Number:	CP0805B1890AWTR
Manufacturer / Brand:	AVX Corporation
Mombamomba ny vokatra	RF DIR COUPLER 1.88-1.9GHZ 0805
Datasheets:	CP0805B1890AWTR.pdf
RoHS Status	Mitahiry ny lead / RoHS tsy mifanaraka
Stock Condition	307146 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of CP0805B1890AWTR

PART NUMBER	CP0805B1890AWTR
MANUFACTURER	AVX Corporation
DESCRIPTION	RF DIR COUPLER 1.88-1.9GHZ 0805
LEAD FREE STATUS / ROHS STATUS	Mitahiry ny lead / RoHS tsy mifanaraka
QUANTITY AVAILABLE	307146 pcs
TAKELA-DAZA	CP0805B1890AWTR.pdf
PACKAGE DEVICE DEVICE	0805
SERIES	-
RETURN LOSS	-25dB
POWER - MAX	3W
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
FITOKANA-MONINA	-25dB
LOZAM-PIFAMOIVOIZANA	0.3dB
FREQUENCY	1.88GHz ~ 1.9GHz
DETAILED DESCRIPTION	RF Directional Coupler DECT 1.88GHz ~ 1.9GHz 15 ± 1dB 3W 0805 (2012 Metric)
MPIFANARAKA	15 ± 1dB
COUPLER TYPE	Standard
APPLICATIONS	DECT

Related Tags

AVX Corporation CP0805B1890AWTR	CP0805B1890AWTR Distributor	CP0805B1890AWTR Supplier
CP0805B1890AWTR Price	CP0805B1890AWTR Pictures	CP0805B1890AWTR Image
CP0805B1890AWTR PDF Datasheet	CP0805B1890AWTR Download Datasheet	CP0805B1890AWTR Datasheet
CP0805B1890AWTR Stock	Buy CP0805B1890AWTR	Buy AVX Corporation CP0805B1890AWTR
AVX Corporation CP0805B1890AWTR	AVX Corporation Supplier	AVX Corporation Distributor
AVX Corporation CP0805B1890AWTR	AVX Corporation [MIL] CP0805B1890AWTR	

Related Products

<p>CP0805B1907AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.895-1.92GHZ 0805 Ao amin'ny staoky: 275429 pcs</p> <p>RFQ</p>	<p>CP0805B1842CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.805-1.88GHZ 0805 Ao amin'ny staoky: 244149 pcs</p> <p>RFQ</p>
<p>CP0805B1880BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.895-1.91GHZ 0805 Ao amin'ny staoky: 306200 pcs</p> <p>RFQ</p>	<p>CP0805B1916CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.916GHZ 0805 Ao amin'ny staoky: 277806 pcs</p> <p>RFQ</p>
<p>CP0805B1842BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.805-1.88GHZ 0805 Ao amin'ny staoky: 303740 pcs</p> <p>RFQ</p>	<p>CP0805B1890CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.88-1.9GHZ 0805 Ao amin'ny staoky: 236269 pcs</p> <p>RFQ</p>
<p>CP0805B1890BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.805-1.9GHZ 0805 Ao amin'ny staoky: 286791 pcs</p> <p>RFQ</p>	<p>CP0805B1880AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0805 Ao amin'ny staoky: 252234 pcs</p> <p>RFQ</p>
<p>CP0805B1907BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.895-1.92GHZ 0805 Ao amin'ny staoky: 292009 pcs</p> <p>RFQ</p>	<p>CP0805B1842AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.805-1.88GHZ 0805 Ao amin'ny staoky: 242457 pcs</p> <p>RFQ</p>
<p>CP0805B1880CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0805 Ao amin'ny staoky: 254080 pcs</p> <p>RFQ</p>	<p>CP0805B1950CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.95GHZ 0805 Ao amin'ny staoky: 311049 pcs</p> <p>RFQ</p>