



45-CBSA-1.0X5.5X0.4

| | |
|-----------------------|---|
| Part Number: | 45-CBSA-1.0X5.5X0.4 |
| Manufacturer / Brand: | Leader Tech Inc. |
| Mombamomba ny vokatra | 45 SERIES CBS SHIELD ASSEMBLY |
| Datasheets: | 45-CBSA-1.0X5.5X0.4.pdf |
| RoHs Status | Lead free / RoHS compliant |
| Stock Condition | 4488 pcs stock |
| Ship From | Hong Kong |
| Shipment Way | DHL/Fedex/TNT/UPS/EMS |

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of 45-CBSA-1.0X5.5X0.4

| | |
|---------------------------------|---|
| PART NUMBER | 45-CBSA-1.0X5.5X0.4 |
| MANUFACTURER | Leader Tech Inc. |
| DESCRIPTION | 45 SERIES CBS SHIELD ASSEMBLY |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS compliant |
| QUANTITY AVAILABLE | 4488 pcs |
| TAKELA-DAZA | 45-CBSA-1.0X5.5X0.4.pdf |
| AMBONY - AMBANY | 1.000" (25.40mm) |
| RIVOTRA | Vent Holes in Pattern |
| TYPE | Shield, 2-Piece |
| SERIES | 40-CBS |
| FONOSANA | Bulk |
| TENDROMBOHITRA | Through Hole |
| NY HAAVON'NY FAHITAN-TORY (MSL) | 1 (Unlimited) |
| LENGTH - AMIN'NY ANKAPOBENY | 5.500" (139.70mm) |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| HEIGHT - OVERALL | 0.400" (10.16mm) |
| DETAILED DESCRIPTION | RF Shield Shield, 2-Piece 1.000" (25.40mm) X 5.500" (139.70mm) Vent Holes in Pattern Through Hole |

Related Tags

| | | |
|--------------------------------------|--|--|
| Leader Tech Inc. 45-CBSA-1.0X5.5X0.4 | 45-CBSA-1.0X5.5X0.4 Distributor | 45-CBSA-1.0X5.5X0.4 Supplier |
| 45-CBSA-1.0X5.5X0.4 Price | 45-CBSA-1.0X5.5X0.4 Pictures | 45-CBSA-1.0X5.5X0.4 Image |
| 45-CBSA-1.0X5.5X0.4 PDF Datasheet | 45-CBSA-1.0X5.5X0.4 Download Datasheet | 45-CBSA-1.0X5.5X0.4 Datasheet |
| 45-CBSA-1.0X5.5X0.4 Stock | Buy 45-CBSA-1.0X5.5X0.4 | Buy Leader Tech Inc. 45-CBSA-1.0X5.5X0.4 |
| Leader Tech Inc. 45-CBSA-1.0X5.5X0.4 | Leader Tech Inc. Supplier | Leader Tech Inc. Distributor |
| Leader Tech Inc. 45-CBSA-1.0X5.5X0.4 | | |

Related Products

| | |
|---|--|
| <p>45-CBSA-1.0X4.5X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4401 pcs RFQ</p> | <p>45-CBSA-1.25X1.75X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 5768 pcs RFQ</p> |
| <p>45-CBSA-1.0X4.25X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4876 pcs RFQ</p> | <p>45-CBSA-1.0X4.75X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4608 pcs RFQ</p> |
| <p>45-CBSA-1.25X1.25X0.4 Manufacturers: Leader Tech Inc. Description: 45-CBSA-1.25X1.25X0.4--45S79--CI Ao amin'ny staoky: 8262 pcs RFQ</p> | <p>45-CBSA-1.0X6.0X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4130 pcs RFQ</p> |
| <p>45-CBSA-1.25X1.5X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 5965 pcs RFQ</p> | <p>45-CBSA-1.0X5.75X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 3885 pcs RFQ</p> |
| <p>45-CBSA-1.25X2.0X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4955 pcs RFQ</p> | <p>45-CBSA-1.0X5.25X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 3716 pcs RFQ</p> |
| <p>45-CBSA-1.0X5.0X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4027 pcs RFQ</p> | <p>45-CBSA-1.0X4.0X0.4 Manufacturers: Leader Tech Inc. Description: 45 SERIES CBS SHIELD ASSEMBLY Ao amin'ny staoky: 4660 pcs RFQ</p> |