



Aeroflex (MACOM Technology Solutions)

MACP-011035

Part Number:	MACP-011035
Manufacturer / Brand:	Aeroflex (MACOM Technology Solutions)
Mombamomba ny vokatra	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
Datasheets:	MACP-011035.pdf
RoHS Status	Lead free / RoHS compliant
Stock Condition	31816 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

Solutions



Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of MACP-011035

PART NUMBER	MACP-011035
MANUFACTURER	Aeroflex (MACOM Technology Solutions)
DESCRIPTION	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	31816 pcs
TAKELA-DAZA	MACP-011035.pdf
PACKAGE DEVICE DEVICE	6-SMD
SERIES	-
RETURN LOSS	-21dB
POWER - MAX	0.5W
FONOSANA	Cut Tape (CT)
PACKAGE / CASE	6-SMD
ANARANA HAFA	1465-1808-1
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	29dB
LOZAM-PIFAMOIVOIZANA	-
FREQUENCY	5MHz ~ 1.2GHz
DETAILED DESCRIPTION	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 12dB 0.5W 6-SMD
MPIFANARAKA	12dB
COUPLER TYPE	Standard
APPLICATIONS	General Purpose

Related Tags

Aeroflex (MACOM Technology Solutions) MACP-011035	MACP-011035 Distributor	MACP-011035 Supplier
MACP-011035 Price	MACP-011035 Pictures	MACP-011035 Image
MACP-011035 PDF Datasheet	MACP-011035 Download Datasheet	MACP-011035 Datasheet
MACP-011035 Stock	Buy MACP-011035	Buy Aeroflex (MACOM Technology Solutions) MACP-011035
Aeroflex (MACOM Technology Solutions) MACP-011035	Aeroflex (MACOM Technology Solutions) Supplier	Aeroflex (MACOM Technology Solutions) Distributor
Aeroflex (MACOM Technology Solutions) MACP-011035	Aeroflex Circuit Technology MACP-011035	Aeroflex MACP-011035
Aeroflex (MACOM Technology Solutions) MACP-011035	Aeroflex Metelics, Division of MACOM MACP-011035	M/A-Com Technology Solutions MACP-011035
Metelics (MACOM Technology Solutions) MACP-011035	MACOM Technology Solutions MACP-011035	

Related Products

<p>MACP-011032 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 33983 pcs</p> <p>RFQ</p>	<p>MACP-011033 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 34032 pcs</p> <p>RFQ</p>
<p>MACP-011013 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Ao amin'ny staoky: 75305 pcs</p> <p>RFQ</p>	<p>MACP-010563-001SMB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-010563-TR100 Ao amin'ny staoky: 4608 pcs</p> <p>RFQ</p>
<p>MACP-011014 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Ao amin'ny staoky: 34558 pcs</p> <p>RFQ</p>	<p>MACP-011010 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 69745 pcs</p> <p>RFQ</p>
<p>MACP-011034 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 34659 pcs</p> <p>RFQ</p>	<p>MACP-011036 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 4034 pcs</p> <p>RFQ</p>
<p>MACPCT0030 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 27402 pcs</p> <p>RFQ</p>	<p>MACP-011015 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD Ao amin'ny staoky: 24969 pcs</p> <p>RFQ</p>
<p>MACP-011038 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 5028 pcs</p> <p>RFQ</p>	<p>MACP-010563-TR1000 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Ao amin'ny staoky: 4446 pcs</p> <p>RFQ</p>

