



Johanson Technology

0898CD15C1748E

Part Number:	0898CD15C1748E
Manufacturer / Brand:	Johanson Technology
Mombamomba ny vokatra	RF DIR COUPLER 880-915MHZ 0805
Datasheets:	0898CD15C1748E.pdf
RoHs Status	Mialà amin'ny fanavotana / RoHS mifehy
Stock Condition	3022 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of 0898CD15C1748E

PART NUMBER	0898CD15C1748E
MANUFACTURER	Johanson Technology
DESCRIPTION	RF DIR COUPLER 880-915MHZ 0805
LEAD FREE STATUS / ROHS STATUS	Mialà amin'ny fanavotana / RoHS mifehy
QUANTITY AVAILABLE	3022 pcs
TAKELA-DAZA	0898CD15C1748E.pdf
PACKAGE DEVICE DEVICE	0805
SERIES	-
RETURN LOSS	10.9dB
POWER - MAX	-
FONOSANA	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric)
ANARANA HAFA	712-1139-1
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free by exemption / RoHS Compliant
FITOKANA-MONINA	35dB
LOZAM-PIFAMOIVOIZANA	0.35dB, 0.45dB
FREQUENCY	880MHz ~ 915MHz, 1.71GHz ~ 1.785GHz
DETAILED DESCRIPTION	RF Directional Coupler 880MHz ~ 915MHz, 1.71GHz ~ 1.785GHz 19.2 ± 1dB, 14 ± 1.5dB 0805 (2012 Metric)
MPIFANARAKA	19.2 ± 1dB, 14 ± 1.5dB
COUPLER TYPE	Dual Band, Dual Path
APPLICATIONS	-

Related Tags

Johanson Technology 0898CD15C1748E	0898CD15C1748E Distributor	0898CD15C1748E Supplier
0898CD15C1748E Price	0898CD15C1748E Pictures	0898CD15C1748E Image
0898CD15C1748E PDF Datasheet	0898CD15C1748E Download Datasheet	0898CD15C1748E Datasheet
0898CD15C1748E Stock	Buy 0898CD15C1748E	Buy Johanson Technology 0898CD15C1748E
Johanson Technology 0898CD15C1748E	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 0898CD15C1748E	Johanson 0898CD15C1748E	Johanson Technology Inc. 0898CD15C1748E

Related Products

<p>0898CP15A035E Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0805 Ao amin'ny staoky: 3244 pcs</p> <p>RFQ</p>	<p>0897621625 Manufacturers: Affinity Medical Technologies - a Molex company Description: CBL ASSY 2.92MM PLUG-PLUG 10' Ao amin'ny staoky: 4918 pcs</p> <p>RFQ</p>
<p>0897621623 Manufacturers: Affinity Medical Technologies - a Molex company Description: CBL ASSY 2.92MM PLUG-PLUG 15" Ao amin'ny staoky: 3094 pcs</p> <p>RFQ</p>	<p>0898CP14C0035T Manufacturers: Johanson Technology Description: RF DIR COUPLER 89MHZ 0603 Ao amin'ny staoky: 305914 pcs</p> <p>RFQ</p>
<p>0898CF15A035E Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0805 Ao amin'ny staoky: 138241 pcs</p> <p>RFQ</p>	<p>0897621900 Manufacturers: Affinity Medical Technologies - a Molex company Description: CBL ASSY SMP JACK-JACK .086 Ao amin'ny staoky: 2354 pcs</p> <p>RFQ</p>
<p>0897621624 Manufacturers: Affinity Medical Technologies - a Molex company Description: CBL ASSY 2.92MM PLUG-PLUG 18" Ao amin'ny staoky: 6850 pcs</p> <p>RFQ</p>	<p>0898CD15B1748E Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0805 Ao amin'ny staoky: 2707 pcs</p> <p>RFQ</p>
<p>0897621622 Manufacturers: Affinity Medical Technologies - a Molex company Description: CBL ASSY 2.92MM PLUG-PLUG 12" Ao amin'ny staoky: 4125 pcs</p> <p>RFQ</p>	<p>0898CP14B035T Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0603 Ao amin'ny staoky: 4717 pcs</p> <p>RFQ</p>
<p>0898CP14A035 Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0603 Ao amin'ny staoky: 3570 pcs</p> <p>RFQ</p>	<p>0898CP14A035T Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0603 Ao amin'ny staoky: 6141 pcs</p> <p>RFQ</p>

