



AVX Corporation

CP0603B1950BWTR

Part Number:	CP0603B1950BWTR
Manufacturer / Brand:	AVX Corporation
Mombamomba ny vokatra	RF DIR COUPLER 1.95GHZ 0603
Datasheets:	CP0603B1950BWTR.pdf
RoHS Status	Lead free / RoHS compliant
Stock Condition	354113 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of CP0603B1950BWTR

PART NUMBER	CP0603B1950BWTR
MANUFACTURER	AVX Corporation
DESCRIPTION	RF DIR COUPLER 1.95GHZ 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	354113 pcs
TAKELA-DAZA	CP0603B1950BWTR.pdf
PACKAGE DEVICE DEVICE	0603
SERIES	-
RETURN LOSS	-
POWER - MAX	3W
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
ANARANA Hafa	CP0603B1950BW CP0603B1950BW-ND
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	-
LOZAM-PIFAMOIVOIZANA	-
FREQUENCY	1.95GHz
DETAILED DESCRIPTION	RF Directional Coupler 1.95GHz 3W 0603 (1608 Metric)
MPIFANARAKA	-
COUPLER TYPE	Standard
APPLICATIONS	-

Related Tags

AVX Corporation CP0603B1950BWTR	CP0603B1950BWTR Distributor	CP0603B1950BWTR Supplier
CP0603B1950BWTR Price	CP0603B1950BWTR Pictures	CP0603B1950BWTR Image
CP0603B1950BWTR PDF Datasheet	CP0603B1950BWTR Download Datasheet	CP0603B1950BWTR Datasheet
CP0603B1950BWTR Stock	Buy CP0603B1950BWTR	Buy AVX Corporation CP0603B1950BWTR
AVX Corporation CP0603B1950BWTR	AVX Corporation Supplier	AVX Corporation Distributor
AVX Corporation CP0603B1950BWTR	AVX Corporation [MIL] CP0603B1950BWTR	

Related Products

<p>CP0603B1747CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 358445 pcs</p> <p>RFQ</p>	<p>CP0603B1880BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0603 Ao amin'ny staoky: 408319 pcs</p> <p>RFQ</p>
<p>CP0603B2442BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 2.4-2.484GHZ 0603 Ao amin'ny staoky: 439563 pcs</p> <p>RFQ</p>	<p>CP0603B1960CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.93-1.99GHZ 0603 Ao amin'ny staoky: 386315 pcs</p> <p>RFQ</p>
<p>CP0603B1880AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0603 Ao amin'ny staoky: 447450 pcs</p> <p>RFQ</p>	<p>CP0603B1960AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.93-1.99GHZ 0603 Ao amin'ny staoky: 409109 pcs</p> <p>RFQ</p>
<p>CP0603B1960BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.93-1.99GHZ 0603 Ao amin'ny staoky: 366828 pcs</p> <p>RFQ</p>	<p>CP0603B1950AW Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.95GHZ 0603 Ao amin'ny staoky: 3707 pcs</p> <p>RFQ</p>
<p>CP0603B1842CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.805-1.88GHZ 0603 Ao amin'ny staoky: 428475 pcs</p> <p>RFQ</p>	<p>CP0603B1842BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.805-1.88GHZ 0603 Ao amin'ny staoky: 423046 pcs</p> <p>RFQ</p>
<p>CP0603B2442AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 2.4-2.484GHZ 0603 Ao amin'ny staoky: 394521 pcs</p> <p>RFQ</p>	<p>CP0603B1950CW Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.95GHZ 0603 Ao amin'ny staoky: 3314 pcs</p> <p>RFQ</p>

