



AVX Corporation

CP0603A1747CLTR

Part Number:	CP0603A1747CLTR
Manufacturer / Brand:	AVX Corporation
Mombamomba ny vokatra	RF DIR COUPLR 1.71-1.785GHZ 0603
Datasheets:	CP0603A1747CLTR.pdf
RoHS Status	Mitahiry ny lead / RoHS tsy mifanaraka
Stock Condition	448804 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of CP0603A1747CLTR

PART NUMBER	CP0603A1747CLTR
MANUFACTURER	AVX Corporation
DESCRIPTION	RF DIR COUPLR 1.71-1.785GHZ 0603
LEAD FREE STATUS / ROHS STATUS	Mitahiry ny lead / RoHS tsy mifanaraka
QUANTITY AVAILABLE	448804 pcs
TAKELA-DAZA	CP0603A1747CLTR.pdf
PACKAGE DEVICE DEVICE	0603
SERIES	-
RETURN LOSS	18dB
POWER - MAX	3W
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
FITOKANA-MONINA	-34dB
LOZAM-PIFAMOIVOIZANA	0.8dB
FREQUENCY	1.71GHz ~ 1.785GHz
DETAILED DESCRIPTION	RF Directional Coupler PCN 1.71GHz ~ 1.785GHz 9.5dB 3W 0603 (1608 Metric)
MPIFANARAKA	9.5dB
COUPLER TYPE	Standard
APPLICATIONS	PCN

Related Tags

AVX Corporation CP0603A1747CLTR	CP0603A1747CLTR Distributor	CP0603A1747CLTR Supplier
CP0603A1747CLTR Price	CP0603A1747CLTR Pictures	CP0603A1747CLTR Image
CP0603A1747CLTR PDF Datasheet	CP0603A1747CLTR Download Datasheet	CP0603A1747CLTR Datasheet
CP0603A1747CLTR Stock	Buy CP0603A1747CLTR	Buy AVX Corporation CP0603A1747CLTR
AVX Corporation CP0603A1747CLTR	AVX Corporation Supplier	AVX Corporation Distributor
AVX Corporation CP0603A1747CLTR	AVX Corporation [MIL] CP0603A1747CLTR	

Related Products

<p>CP0603A1747MLTR\500 Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 414670 pcs</p> <p>RFQ</p>	<p>CP0603A1575DWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 370445 pcs</p> <p>RFQ</p>
<p>CP0603A1842CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.805-1.88GHZ 0603 Ao amin'ny staoky: 440903 pcs</p> <p>RFQ</p>	<p>CP0603A1600CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.6GHZ 0603 Ao amin'ny staoky: 381924 pcs</p> <p>RFQ</p>
<p>CP0603A1767MNTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.767GHZ 0603 Ao amin'ny staoky: 394933 pcs</p> <p>RFQ</p>	<p>CP0603A1747MLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.71-1.785GHZ 0603 Ao amin'ny staoky: 489317 pcs</p> <p>RFQ</p>
<p>CP0603A1747DWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 372538 pcs</p> <p>RFQ</p>	<p>CP0603A1441DWTR Manufacturers: AVX Corporation Description: RF DIR COUPL 1.429-1.453GHZ 0603 Ao amin'ny staoky: 372349 pcs</p> <p>RFQ</p>
<p>CP0603A1747CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 366303 pcs</p> <p>RFQ</p>	<p>CP0603A1441CWTR Manufacturers: AVX Corporation Description: RF DIR COUPL 1.429-1.453GHZ 0603 Ao amin'ny staoky: 430782 pcs</p> <p>RFQ</p>
<p>CP0603A1747BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 Ao amin'ny staoky: 458605 pcs</p> <p>RFQ</p>	<p>CP0603A1550AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.55GHZ 0603 Ao amin'ny staoky: 345160 pcs</p> <p>RFQ</p>

