



TDK Corporation

HHM2910E1

Part Number:	HHM2910E1
Manufacturer / Brand:	TDK Corporation
Mombamomba ny vokatra	RF DIR COUPLER 1.71GHZ-2.03GHZ
Datasheets:	HHM2910E1.pdf
RoHs Status	Lead free / RoHS compliant
Stock Condition	300204 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of HHM2910E1

PART NUMBER	HHM2910E1
MANUFACTURER	TDK Corporation
DESCRIPTION	RF DIR COUPLER 1.71GHZ-2.03GHZ
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	300204 pcs
TAKELA-DAZA	HHM2910E1.pdf
SERIES	HHM
RETURN LOSS	-
POWER - MAX	-
FONOSANA	Original-Reel®
PACKAGE / CASE	0402 (1005 Metric), 4 PC Pad
ANARANA Hafa	445-172643-6
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	34dB
LOZAM-PIFAMOIVOIZANA	0.25dB
FREQUENCY	1.71GHz ~ 2.03GHz
DETAILED DESCRIPTION	RF Directional Coupler 1.71GHz ~ 2.03GHz 21.2 ± 1dB 0402 (1005 Metric), 4 PC Pad
MPIFANARAKA	21.2 ± 1dB
COUPLER TYPE	Standard
APPLICATIONS	-

Related Tags

TDK Corporation HHM2910E1	HHM2910E1 Distributor	HHM2910E1 Supplier
HHM2910E1 Price	HHM2910E1 Pictures	HHM2910E1 Image
HHM2910E1 PDF Datasheet	HHM2910E1 Download Datasheet	HHM2910E1 Datasheet
HHM2910E1 Stock	Buy HHM2910E1	Buy TDK Corporation HHM2910E1
TDK Corporation HHM2910E1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM2910E1		

Related Products

<p>HHM2319B2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 824-915MHZ 0805 Ao amin'ny staoky: 561662 pcs</p> <p>RFQ</p>	<p>HHM2909C4 Manufacturers: TDK Corporation Description: RF DIR COUPLER 777-925MHZ 0402 Ao amin'ny staoky: 881596 pcs</p> <p>RFQ</p>
<p>HHM2220SA3 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.92-1.98GHZ 0603 Ao amin'ny staoky: 72297 pcs</p> <p>RFQ</p>	<p>HHM2917B1 Manufacturers: TDK Corporation Description: RF DIR COUPLER 2.4-2.5GHZ 0402 Ao amin'ny staoky: 348500 pcs</p> <p>RFQ</p>
<p>HHM2915A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 0402 Ao amin'ny staoky: 1013985 pcs</p> <p>RFQ</p>	<p>HHM2510B1 Manufacturers: TDK Corporation Description: RF DIR COUPLER 2.4-2.5GHZ 0202 Ao amin'ny staoky: 294482 pcs</p> <p>RFQ</p>
<p>HHM2910E4 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71GHZ-1.98GHZ Ao amin'ny staoky: 383268 pcs</p> <p>RFQ</p>	<p>HHM2919A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 2.4-2.5GHZ 0402 Ao amin'ny staoky: 880371 pcs</p> <p>RFQ</p>
<p>HHM2933A1 Manufacturers: TDK Corporation Description: RF DIR COUPLER 2.4-2.5GHZ 0402 Ao amin'ny staoky: 1018819 pcs</p> <p>RFQ</p>	<p>HHM2293A1 Manufacturers: TDK Corporation Description: MULTILAYER DIVIDER FOR W-LAN/BLU Ao amin'ny staoky: 909724 pcs</p> <p>RFQ</p>
<p>HHM2215SA5 Manufacturers: TDK Corporation Description: RF DIR COUPLER 824-915MHZ 0603 Ao amin'ny staoky: 75095 pcs</p> <p>RFQ</p>	<p>HHM2942A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 2.4-2.5GHZ 0402 Ao amin'ny staoky: 1115188 pcs</p> <p>RFQ</p>

