



TDK Corporation

HHM1732B1

Part Number:	HHM1732B1
Manufacturer / Brand:	TDK Corporation
Mombamomba ny vokatra	BALUN 4.9GHZ-5.95GHZ 50/100 0603
Datasheets:	HHM1732B1.pdf
RoHs Status	Lead free / RoHS compliant
Stock Condition	273182 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of HHM1732B1

PART NUMBER	HHM1732B1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 4.9GHZ-5.95GHZ 50/100 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	273182 pcs
TAKELA-DAZA	HHM1732B1.pdf
SERIES	HHM
MIVERINA MITSOAKA (MIN)	10dB
DINGANA FIVOAHANA	180° ±10°
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
ANARANA Hafa	445-3247-2
TENDROMBOHITRA	Surface Mount
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ADI-HEVITRA MITOKA-MONINA (MAX)	1.0dB
IMPEDANCE - TSY MITOVY / MANDANJALANJA	50 / 100 Ohm
FREQUENCY FREQUENCY	4.9GHz ~ 5.95GHz
DETAILED DESCRIPTION	RF Balun 4.9GHz ~ 5.95GHz 50 / 100 Ohm 0603 (1608 Metric)

Related Tags

TDK Corporation HHM1732B1	HHM1732B1 Distributor	HHM1732B1 Supplier
HHM1732B1 Price	HHM1732B1 Pictures	HHM1732B1 Image
HHM1732B1 PDF Datasheet	HHM1732B1 Download Datasheet	HHM1732B1 Datasheet
HHM1732B1 Stock	Buy HHM1732B1	Buy TDK Corporation HHM1732B1
TDK Corporation HHM1732B1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1732B1		

Related Products

<p>HHM17166A1 Manufacturers: TDK Corporation Description: BALUN 1.9GHZ-2.3GHZ 50/50 0603 Ao amin'ny staoky: 247743 pcs</p> <p>RFQ</p>	<p>HHM1726N1 Manufacturers: TDK Corporation Description: BALUN 824MHZ-915MHZ 50/100 0603 Ao amin'ny staoky: 769871 pcs</p> <p>RFQ</p>
<p>HHM1775D1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Ao amin'ny staoky: 261546 pcs</p> <p>RFQ</p>	<p>HHM1727D1 Manufacturers: TDK Corporation Description: BALUN 3.3GHZ-3.9GHZ 50/50 0603 Ao amin'ny staoky: 238503 pcs</p> <p>RFQ</p>
<p>HHM1763B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0603 Ao amin'ny staoky: 72443 pcs</p> <p>RFQ</p>	<p>HHM1733B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0603 Ao amin'ny staoky: 144005 pcs</p> <p>RFQ</p>
<p>HHM1726P1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/100 0603 Ao amin'ny staoky: 981103 pcs</p> <p>RFQ</p>	<p>HHM1752A2 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 Ao amin'ny staoky: 115644 pcs</p> <p>RFQ</p>
<p>HHM17168B1 Manufacturers: TDK Corporation Description: BALUN 3.4GHZ-3.8GHZ 50/50 0603 Ao amin'ny staoky: 227544 pcs</p> <p>RFQ</p>	<p>HHM1776B2 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0603 Ao amin'ny staoky: 57084 pcs</p> <p>RFQ</p>
<p>HHM1731F1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.88GHZ 50/200 0603 Ao amin'ny staoky: 821085 pcs</p> <p>RFQ</p>	<p>HHM1749S1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0603 Ao amin'ny staoky: 800377 pcs</p> <p>RFQ</p>

