



TDK Corporation

## HHM17166A1

Part Number:	HHM17166A1
Manufacturer / Brand:	TDK Corporation
Mombamomba ny vokatra	BALUN 1.9GHZ-2.3GHZ 50/50 0603
Datasheets:	<a href="#">HHM17166A1.pdf</a>
RoHs Status	Lead free / RoHS compliant
Stock Condition	247743 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

**MANGATAHA FAMPISEHOANA**

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

### Specifications of HHM17166A1

PART NUMBER	HHM17166A1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 1.9GHZ-2.3GHZ 50/50 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	247743 pcs
TAKELA-DAZA	<a href="#">HHM17166A1.pdf</a>
SERIES	-
MIVERINA MITSOAKA (MIN)	-10.3dB
DINGANA FIVOAHAHA	178°
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
ANARANA HAFA	445-173036-2
TENDROMBOHITRA	Surface Mount
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ADI-HEVITRA MITOKA-MONINA (MAX)	1.5dB
IMPEDANCE - TSY MITOVY / MANDANJALANJA	50 / 50 Ohm
FREQUENCY FREQUENCY	1.9GHz ~ 2.3GHz
DETAILED DESCRIPTION	RF Balun 1.9GHz ~ 2.3GHz 50 / 50 Ohm 0603 (1608 Metric)

### Related Tags

TDK Corporation HHM17166A1	HHM17166A1 Distributor	HHM17166A1 Supplier
HHM17166A1 Price	HHM17166A1 Pictures	HHM17166A1 Image
HHM17166A1 PDF Datasheet	HHM17166A1 Download Datasheet	HHM17166A1 Datasheet
HHM17166A1 Stock	Buy HHM17166A1	Buy TDK Corporation HHM17166A1
TDK Corporation HHM17166A1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM17166A1		

### Related Products

<p><b>HHM17152A1</b> Manufacturers: TDK Corporation Description: BALUN 698MHZ-894MHZ 50/100 0603 Ao amin'ny staoky: 506941 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1727D1</b> Manufacturers: TDK Corporation Description: BALUN 3.3GHZ-3.9GHZ 50/50 0603 Ao amin'ny staoky: 238503 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1715E1</b> Manufacturers: TDK Corporation Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 Ao amin'ny staoky: 54435 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17146A1</b> Manufacturers: TDK Corporation Description: BALUN 1.92GHZ-2.17GHZ 50/50 0603 Ao amin'ny staoky: 920864 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17144A1</b> Manufacturers: TDK Corporation Description: BALUN 791MHZ-960MHZ 50/100 0603 Ao amin'ny staoky: 862583 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1732B1</b> Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603 Ao amin'ny staoky: 273182 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1726N1</b> Manufacturers: TDK Corporation Description: BALUN 824MHZ-915MHZ 50/100 0603 Ao amin'ny staoky: 769871 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17168B1</b> Manufacturers: TDK Corporation Description: BALUN 3.4GHZ-3.8GHZ 50/50 0603 Ao amin'ny staoky: 227544 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1726P1</b> Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/100 0603 Ao amin'ny staoky: 981103 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17153A2</b> Manufacturers: TDK Corporation Description: BALUN 698MHZ-894MHZ 50/50 0603 Ao amin'ny staoky: 387125 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1731F1</b> Manufacturers: TDK Corporation Description: BALUN 1.71-1.88GHZ 50/200 0603 Ao amin'ny staoky: 821085 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17165A1</b> Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.8GHZ 50/50 0603 Ao amin'ny staoky: 273962 pcs</p> <p><b>RFQ</b></p>

