



TDK Corporation

## HHM1711D1

Part Number:	HHM1711D1
Manufacturer / Brand:	TDK Corporation
Mombamomba ny vokatra	BALUN 2.4GHZ-2.5GHZ 50/100 0603
Datasheets:	<a href="#">HHM1711D1.pdf</a>
RoHS Status	Lead free / RoHS compliant
Stock Condition	180690 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

**MANGATAHA FAMPISEHOANA**

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

### Specifications of HHM1711D1

PART NUMBER	HHM1711D1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 50/100 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	180690 pcs
TAKELA-DAZA	<a href="#">HHM1711D1.pdf</a>
SERIES	HHM
MIVERINA MITSOAKA (MIN)	10dB
DINGANA FIVOAHANA	180° ±10°
FONOSANA	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric)
ANARANA Hafa	445-1232-1
TENDROMBOHITRA	Surface Mount
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ADI-HEVITRA MITOKA-MONINA (MAX)	1.2dB
IMPEDANCE - TSY MITOVY / MANDANJALANJA	50 / 100 Ohm
FREQUENCY FREQUENCY	2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Balun 2.4GHz ~ 2.5GHz 50 / 100 Ohm 0603 (1608 Metric)

### Related Tags

TDK Corporation HHM1711D1	HHM1711D1 Distributor	HHM1711D1 Supplier
HHM1711D1 Price	HHM1711D1 Pictures	HHM1711D1 Image
HHM1711D1 PDF Datasheet	HHM1711D1 Download Datasheet	HHM1711D1 Datasheet
HHM1711D1 Stock	Buy HHM1711D1	Buy TDK Corporation HHM1711D1
TDK Corporation HHM1711D1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1711D1		

### Related Products

<p><b>HHM1595A1</b> Manufacturers: TDK Corporation Description: BALUN 3GHZ-8GHZ 50/100 0805 Ao amin'ny staoky: 163352 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17125D1</b> Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Ao amin'ny staoky: 496156 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17139B2</b> Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.6GHZ 50/50 0603 Ao amin'ny staoky: 823244 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711Q1</b> Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-3.8GHZ 50/100 0603 Ao amin'ny staoky: 836875 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1589E1</b> Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/200 0805 Ao amin'ny staoky: 435579 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1710D1</b> Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Ao amin'ny staoky: 460907 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1596A1</b> Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Ao amin'ny staoky: 493437 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17144A1</b> Manufacturers: TDK Corporation Description: BALUN 791MHZ-960MHZ 50/100 0603 Ao amin'ny staoky: 862583 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711E1</b> Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Ao amin'ny staoky: 796296 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1603A1</b> Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD Ao amin'ny staoky: 120843 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1591D1</b> Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/100 0805 Ao amin'ny staoky: 466597 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17139B1</b> Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Ao amin'ny staoky: 255709 pcs</p> <p><b>RFQ</b></p>

