



Aeroflex (MACOM Technology Solutions)

MACP-009596-CA0160

Part Number:	MACP-009596-CA0160
Manufacturer / Brand:	Aeroflex (MACOM Technology Solutions)
Mombamomba ny vokatra	RF DIR COUPLER 5MHZ-1GHZ SM22
Datasheets:	MACP-009596-CA0160.pdf
RoHS Status:	Lead free / RoHS compliant
Stock Condition:	27221 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Solutions



Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of MACP-009596-CA0160

PART NUMBER	MACP-009596-CA0160
MANUFACTURER	Aeroflex (MACOM Technology Solutions)
DESCRIPTION	RF DIR COUPLER 5MHZ-1GHZ SM22
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	27221 pcs
TAKELA-DAZA	MACP-009596-CA0160.pdf
PACKAGE DEVICE DEVICE	SM-22
SERIES	-
RETURN LOSS	-16dB
POWER - MAX	-
FONOSANA	Cut Tape (CT)
PACKAGE / CASE	6-SMD Module
ANARANA HAFA	1465-1321-1
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	-
LOZAM-PIFAMOIVOIZANA	-
FREQUENCY	5MHz ~ 1GHz
DETAILED DESCRIPTION	RF Directional Coupler 5MHz ~ 1GHz 10dB 6-SMD Module
MPIFANARAKA	10dB
COUPLER TYPE	Standard
APPLICATIONS	-

Related Tags

Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	MACP-009596-CA0160 Distributor	MACP-009596-CA0160 Supplier
MACP-009596-CA0160 Price	MACP-009596-CA0160 Pictures	MACP-009596-CA0160 Image
MACP-009596-CA0160 PDF Datasheet	MACP-009596-CA0160 Download Datasheet	MACP-009596-CA0160 Datasheet
MACP-009596-CA0160 Stock	Buy MACP-009596-CA0160	Buy Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex (MACOM Technology Solutions) Supplier	Aeroflex (MACOM Technology Solutions) Distributor
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex Circuit Technology MACP-009596-CA0160	Aeroflex MACP-009596-CA0160
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex Metelics, Division of MACOM MACP-009596-CA0160	M/A-Com Technology Solutions MACP-009596-CA0160
Metelics (MACOM Technology Solutions) MACP-009596-CA0160	MACOM Technology Solutions MACP-009596-CA0160	

Related Products

<p>MACP-008125-CK07TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-008125-CK07F Ao amin'ny staoky: 555 pcs</p> <p>RFQ</p>	<p>MACP-010507-CH0160 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-300MHZ 5SMD Ao amin'ny staoky: 75562 pcs</p> <p>RFQ</p>
<p>MACP-008125-CK07F0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1GHZ SM127 Ao amin'ny staoky: 3506 pcs</p> <p>RFQ</p>	<p>MACP-009596-CA01TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-009596-CA016 Ao amin'ny staoky: 485 pcs</p> <p>RFQ</p>
<p>MACP-007727-CI07B0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ SM123 Ao amin'ny staoky: 55152 pcs</p> <p>RFQ</p>	<p>MACP-009730-C60370 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ MOD Ao amin'ny staoky: 68058 pcs</p> <p>RFQ</p>
<p>MACH102-8TP-R Manufacturers: Belden's Hirschmann Description: NETWORK SWITCH-MANAGED 8 PORT Ao amin'ny staoky: 60 pcs</p> <p>RFQ</p>	<p>MACP-010561-000000 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 2GHZ-6GHZ 6TDFN Ao amin'ny staoky: 4788 pcs</p> <p>RFQ</p>
<p>MACP-009011-C80370 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 29238 pcs</p> <p>RFQ</p>	<p>MACP-010414-CA0370 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 103049 pcs</p> <p>RFQ</p>
<p>MACP-007727-CI07TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-007727-CI07B Ao amin'ny staoky: 583 pcs</p> <p>RFQ</p>	<p>MACP-010250-C808A0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ MOD Ao amin'ny staoky: 114443 pcs</p> <p>RFQ</p>

