

3A0056

Part Number:	3A0056
Manufacturer / Brand:	Anaren
Mombamomba ny vokatra	RF DIR COUPLER 2GHZ-4GHZ MODULE
Datasheets:	3A0056.pdf
RoHS Status	Lead free / RoHS compliant
Stock Condition	122 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of 3A0056

PART NUMBER	3A0056
MANUFACTURER	Anaren
DESCRIPTION	RF DIR COUPLER 2GHZ-4GHZ MODULE
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	122 pcs
TAKELA-DAZA	3A0056.pdf
PACKAGE DEVICE DEVICE	-
SERIES	-
RETURN LOSS	13.2dB
POWER - MAX	100W
FONOSANA	Tray
PACKAGE / CASE	Module
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	19dB
LOZAM-PIFAMOIVOIZANA	0.65dB
FREQUENCY	2GHz ~ 4GHz
DETAILED DESCRIPTION	RF Directional Coupler Military 2GHz ~ 4GHz 3dB 100W Module
MPIFANARAKA	3dB
COUPLER TYPE	Standard
APPLICATIONS	Military

Related Tags

Anaren 3A0056	3A0056 Distributor	3A0056 Supplier
3A0056 Price	3A0056 Pictures	3A0056 Image
3A0056 PDF Datasheet	3A0056 Download Datasheet	3A0056 Datasheet
3A0056 Stock	Buy 3A0056	Buy Anaren 3A0056
Anaren 3A0056	Anaren Supplier	Anaren Distributor
Anaren 3A0056		

Related Products

<p>10262-3 Manufacturers: Anaren Description: RF DIR COUPLER 125MHZ-250MHZ Ao amin'ny staoky: 6453 pcs</p> <p style="text-align: center;">RFQ</p>	<p>X3C19P1-04S Manufacturers: Anaren Description: RF DIR COUPLER 1.7GHZ-2GHZ SMD Ao amin'ny staoky: 47991 pcs</p> <p style="text-align: center;">RFQ</p>
<p>CP0805A1890BWTR\500 Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.88-1.9GHZ 0805 Ao amin'ny staoky: 251680 pcs</p> <p style="text-align: center;">RFQ</p>	<p>3A0368-X Manufacturers: Bussmann (Eaton) Description: LABEL INFORMATION Ao amin'ny staoky: 16815 pcs</p> <p style="text-align: center;">RFQ</p>
<p>CP0603B1950BWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.95GHZ 0603 Ao amin'ny staoky: 354113 pcs</p> <p style="text-align: center;">RFQ</p>	<p>0898CD15B1748E Manufacturers: Johanson Technology Description: RF DIR COUPLER 880-915MHZ 0805 Ao amin'ny staoky: 2707 pcs</p> <p style="text-align: center;">RFQ</p>
<p>3A0055 Manufacturers: Anaren Description: RF DIR COUPLER 1GHZ-2GHZ MODULE Ao amin'ny staoky: 162 pcs</p> <p style="text-align: center;">RFQ</p>	<p>CP0603B0881CWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 869-894MHZ 0603 Ao amin'ny staoky: 340277 pcs</p> <p style="text-align: center;">RFQ</p>
<p>3A0200 Manufacturers: Anaren Description: RF DIR COUPLER 1.3GHZ-2.6GHZ MOD Ao amin'ny staoky: 169 pcs</p> <p style="text-align: center;">RFQ</p>	<p>XC3500P-20S Manufacturers: Anaren Description: RF DIR COUPLER 3.3-3.8GHZ 4SMD Ao amin'ny staoky: 28299 pcs</p> <p style="text-align: center;">RFQ</p>
<p>CP0805B1765AWTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.765GHZ 0805 Ao amin'ny staoky: 260989 pcs</p> <p style="text-align: center;">RFQ</p>	<p>3A0231212A Manufacturers: Sensata Technologies Description: TEMP PROBE SS THERMISTOR 12" WIR Ao amin'ny staoky: 6075 pcs</p> <p style="text-align: center;">RFQ</p>