



Aeroflex (MACOM Technology Solutions)

## MACP-010507-CH0160

Part Number:	MACP-010507-CH0160
Manufacturer / Brand:	Aeroflex (MACOM Technology Solutions)
Mombamomba ny vokatra	RF DIR COUPLER 5MHZ-300MHZ 5SMD
Datasheets:	<a href="#">MACP-010507-CH0160.pdf</a>
RoHS Status	Lead free / RoHS compliant
Stock Condition	75562 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

**MANGATAHA FAMPISEHOANA**

### Solutions



Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

### Specifications of MACP-010507-CH0160

PART NUMBER	MACP-010507-CH0160
MANUFACTURER	Aeroflex (MACOM Technology Solutions)
DESCRIPTION	RF DIR COUPLER 5MHZ-300MHZ 5SMD
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	75562 pcs
TAKELA-DAZA	<a href="#">MACP-010507-CH0160.pdf</a>
PACKAGE DEVICE DEVICE	5-SMD
SERIES	-
RETURN LOSS	31dB
POWER - MAX	500mW
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	5-SMD Module
ANARANA HAFA	1465-1718-2
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	-
LOZAM-PIFAMOIVOIZANA	0.4dB
FREQUENCY	5MHz ~ 300MHz
DETAILED DESCRIPTION	RF Directional Coupler General Purpose 5MHz ~ 300MHz 17dB 500mW 5-SMD Module
MPIFANARAKA	17dB
COUPLER TYPE	Standard
APPLICATIONS	General Purpose

### Related Tags

<a href="#">Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160</a>	<a href="#">MACP-010507-CH0160 Distributor</a>	<a href="#">MACP-010507-CH0160 Supplier</a>
<a href="#">MACP-010507-CH0160 Price</a>	<a href="#">MACP-010507-CH0160 Pictures</a>	<a href="#">MACP-010507-CH0160 Image</a>
<a href="#">MACP-010507-CH0160 PDF Datasheet</a>	<a href="#">MACP-010507-CH0160 Download Datasheet</a>	<a href="#">MACP-010507-CH0160 Datasheet</a>
<a href="#">MACP-010507-CH0160 Stock</a>	<a href="#">Buy MACP-010507-CH0160</a>	<a href="#">Buy Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160</a>
<a href="#">Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160</a>	<a href="#">Aeroflex (MACOM Technology Solutions) Supplier</a>	<a href="#">Aeroflex (MACOM Technology Solutions) Distributor</a>
<a href="#">Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160</a>	<a href="#">Aeroflex Circuit Technology MACP-010507-CH0160</a>	<a href="#">Aeroflex MACP-010507-CH0160</a>
<a href="#">Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160</a>	<a href="#">Aeroflex Metelics, Division of MACOM MACP-010507-CH0160</a>	<a href="#">M/A-Com Technology Solutions MACP-010507-CH0160</a>
<a href="#">Metelics (MACOM Technology Solutions) MACP-010507-CH0160</a>	<a href="#">MACOM Technology Solutions MACP-010507-CH0160</a>	

### Related Products

<p><b>MACP-009730-C60370</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ MOD Ao amin'ny staoky: 68058 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-010561-TR1000</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 2GHZ-6GHZ 6DFN Ao amin'ny staoky: 4662 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>MACP-010562-000000</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 6GHZ-18GHZ 6TDFN Ao amin'ny staoky: 4595 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-010414-CA0370</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 103049 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>MACP-009596-CA01TB</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-009596-CA016 Ao amin'ny staoky: 485 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-009596-CA0160</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1GHZ SM22 Ao amin'ny staoky: 27221 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>MACP-009011-C80370</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ao amin'ny staoky: 29238 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-010562-TR1000</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 6GHZ-18GHZ 6TDFN Ao amin'ny staoky: 3016 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>MACP-010250-C808A0</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 5MHZ-1.2GHZ MOD Ao amin'ny staoky: 114443 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-010562-001SMB</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-010562-TR100 Ao amin'ny staoky: 5017 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>MACP-010561-001SMB</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MACP-010561-TR100 Ao amin'ny staoky: 3678 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>MACP-010561-000000</b> Manufacturers: Aeroflex (MACOM Technology Solutions) Description: RF DIR COUPLER 2GHZ-6GHZ 6TDFN Ao amin'ny staoky: 4788 pcs</p> <p><a href="#">RFQ</a></p>

