




2450BL05A0100T

Part Number:	2450BL05A0100T
Manufacturer / Brand:	Johanson Technology
Mombamomba ny vokatra	BALUN 2.3GHZ-2.69GHZ 50/100 0202
Datasheets:	 2450BL05A0100T.pdf
RoHs Status	 Lead free / RoHS compliant
Stock Condition	346165 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.












Specifications of 2450BL05A0100T

PART NUMBER	2450BL05A0100T
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 2.3GHZ-2.69GHZ 50/100 0202
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	346165 pcs
TAKELA-DAZA	 2450BL05A0100T.pdf
SERIES	2450
MIVERINA MITSOAKA (MIN)	9.5dB
DINGANA FIVOAHANA	180° ±10°
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0202 (0505 Metric), 4 PC Pad
ANARANA Hafa	712-1646-2
TENDROMBOHITRA	Surface Mount
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ADI-HEVITRA MITOKA-MONINA (MAX)	0.55dB
IMPEDANCE - TSY MITOVY / MANDANJALANJA	50 / 100 Ohm
FREQUENCY FREQUENCY	2.3GHz ~ 2.69GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.69GHz 50 / 100 Ohm 0202 (0505 Metric), 4 PC Pad

Related Tags

Johanson Technology 2450BL05A0100T	2450BL05A0100T Distributor	2450BL05A0100T Supplier
2450BL05A0100T Price	2450BL05A0100T Pictures	2450BL05A0100T Image
2450BL05A0100T PDF Datasheet	2450BL05A0100T Download Datasheet	2450BL05A0100T Datasheet
2450BL05A0100T Stock	Buy 2450BL05A0100T	Buy Johanson Technology 2450BL05A0100T
Johanson Technology 2450BL05A0100T	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 2450BL05A0100T	Johanson 2450BL05A0100T	Johanson Technology Inc. 2450BL05A0100T

Related Products

 <p>2450BL07A0050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 Ao amin'ny staoky: 3869 pcs</p> <p>RFQ</p>	 <p>2450AT43H0100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 4372 pcs</p> <p>RFQ</p>
 <p>2450AT43B100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 338380 pcs</p> <p>RFQ</p>	 <p>2450AT43F0100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 112113 pcs</p> <p>RFQ</p>
 <p>2450BL14B050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Ao amin'ny staoky: 2880 pcs</p> <p>RFQ</p>	 <p>2450BL14B200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 Ao amin'ny staoky: 4504 pcs</p> <p>RFQ</p>
 <p>2450BL14B100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Ao amin'ny staoky: 2801 pcs</p> <p>RFQ</p>	 <p>2450AT45A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 194676 pcs</p> <p>RFQ</p>
 <p>2450AT44A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 3720 pcs</p> <p>RFQ</p>	 <p>2450BL14B100 Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Ao amin'ny staoky: 6408 pcs</p> <p>RFQ</p>
 <p>2450BL07A0100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 Ao amin'ny staoky: 6085 pcs</p> <p>RFQ</p>	 <p>2450AT43D100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD Ao amin'ny staoky: 6073 pcs</p> <p>RFQ</p>