



AVX Corporation

CP0402A1950ALTR

Part Number:	CP0402A1950ALTR
Manufacturer / Brand:	AVX Corporation
Mombamomba ny vokatra	RF DIR COUPLER 1.9GHZ 0402
Datasheets:	CP0402A1950ALTR.pdf
RoHS Status	Lead free / RoHS compliant
Stock Condition	414676 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

MANGATAHA FAMPISEHOANA

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

Specifications of CP0402A1950ALTR

PART NUMBER	CP0402A1950ALTR
MANUFACTURER	AVX Corporation
DESCRIPTION	RF DIR COUPLER 1.9GHZ 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	414676 pcs
TAKELA-DAZA	CP0402A1950ALTR.pdf
PACKAGE DEVICE DEVICE	0402
SERIES	-
RETURN LOSS	-
POWER - MAX	3W
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0402 (1005 Metric)
ANARANA HAFANA	CP0402A1950AL CP0402A1950AL-ND
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FITOKANA-MONINA	-
LOZAM-PIFAMOIVOIZANA	-
FREQUENCY	1.9GHz
DETAILED DESCRIPTION	RF Directional Coupler 1.9GHz 3W 0402 (1005 Metric)
MPIFANARAKA	-
COUPLER TYPE	Standard
APPLICATIONS	-

Related Tags

AVX Corporation CP0402A1950ALTR	CP0402A1950ALTR Distributor	CP0402A1950ALTR Supplier
CP0402A1950ALTR Price	CP0402A1950ALTR Pictures	CP0402A1950ALTR Image
CP0402A1950ALTR PDF Datasheet	CP0402A1950ALTR Download Datasheet	CP0402A1950ALTR Datasheet
CP0402A1950ALTR Stock	Buy CP0402A1950ALTR	Buy AVX Corporation CP0402A1950ALTR
AVX Corporation CP0402A1950ALTR	AVX Corporation Supplier	AVX Corporation Distributor
AVX Corporation CP0402A1950ALTR	AVX Corporation [MIL] CP0402A1950ALTR	

Related Products

<p>CP0402A1950CLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.9GHZ 0402 Ao amin'ny staoky: 486772 pcs</p> <p>RFQ</p>	<p>CP0402A1880ENTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0402 Ao amin'ny staoky: 479821 pcs</p> <p>RFQ</p>
<p>CP0402A1950ELTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.9GHZ 0402 Ao amin'ny staoky: 392608 pcs</p> <p>RFQ</p>	<p>CP0402A1890ALTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.88-1.9GHZ 0402 Ao amin'ny staoky: 502970 pcs</p> <p>RFQ</p>
<p>CP0402A1950FLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.9GHZ 0402 Ao amin'ny staoky: 464652 pcs</p> <p>RFQ</p>	<p>CP0402A1880ELTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0402 Ao amin'ny staoky: 415023 pcs</p> <p>RFQ</p>
<p>CP0402A1960ALTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.93-1.99GHZ 0402 Ao amin'ny staoky: 433792 pcs</p> <p>RFQ</p>	<p>CP0402A1950BLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.9GHZ 0402 Ao amin'ny staoky: 487993 pcs</p> <p>RFQ</p>
<p>CP0402A1950DLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.9GHZ 0402 Ao amin'ny staoky: 474253 pcs</p> <p>RFQ</p>	<p>CP0402A1880DNTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0402 Ao amin'ny staoky: 435221 pcs</p> <p>RFQ</p>
<p>CP0402A1890ELTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.88-1.9GHZ 0402 Ao amin'ny staoky: 459521 pcs</p> <p>RFQ</p>	<p>CP0402A1880DLTR Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0402 Ao amin'ny staoky: 459126 pcs</p> <p>RFQ</p>

