



Tamura

## LA01P054S05

Part Number:  
 Manufacturer / Brand:  
 Mombamomba ny vokatra  
 Datasheets:  
 RoHs Status  
 Stock Condition  
 Ship From  
 Shipment Way

LA01P054S05  
 Tamura  
 SENSOR  
 1.LA01P054S05.pdf  
 2.LA01P054S05.pdf  
 Lead free / RoHS compliant  
 8000 pcs stock  
 Hong Kong  
 DHL/Fedex/TNT/UPS/EMS



Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

### Specifications of LA01P054S05

PART NUMBER	LA01P054S05
MANUFACTURER	Tamura
DESCRIPTION	SENSOR
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
QUANTITY AVAILABLE	8000 pcs
TAKELA-DAZA	1.LA01P054S05.pdf 2.LA01P054S05.pdf
VOLTAGE - FITAOVANA	4.5 V ~ 5.5 V
SERIES	LA01P
TADIAVINA	Hall Effect, Open Loop
FAHATSAPANA	40mV/A
TIME RESPONSE	1µs
POLARIZATION	Bidirectional
FONOSANA	Bulk
PACKAGE / CASE	Module
FIVOAHANA	Ratiometric, Voltage
ANARANA HAFA	9-LA01P054S05ZY MT7412
OPERATING TEMPERATURE	-40°C ~ 90°C
ISAN'NY SEHATRA	1
TENDROMBOHITRA	Through Hole
LINEARITY	±1%
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
FREQUENCY	DC ~ 400kHz
FOR MEASUREMENT	AC/DC
DETAILED DESCRIPTION	Current Sensor 54A 1 Channel Hall Effect, Open Loop Bidirectional Module
CURRENT - SUPPLY (MAX)	10mA
CURRENT - SENSING	54A
ARAKA NY MARINA	±1%

### Related Tags

Tamura LA01P054S05	LA01P054S05 Distributor	LA01P054S05 Supplier
LA01P054S05 Price	LA01P054S05 Pictures	LA01P054S05 Image
LA01P054S05 PDF Datasheet	LA01P054S05 Download Datasheet	LA01P054S05 Datasheet
LA01P054S05 Stock	Buy LA01P054S05	Buy Tamura LA01P054S05
Tamura LA01P054S05	Tamura Supplier	Tamura Distributor
Tamura LA01P054S05		

### Related Products

<p><b>LA02P035S03</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 8292 pcs  <a href="#">RFQ</a></p>	<p><b>LA01M041S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 7112 pcs  <a href="#">RFQ</a></p>
<p><b>LA02P054S03</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 6509 pcs  <a href="#">RFQ</a></p>	<p><b>LA02P021S03</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 8433 pcs  <a href="#">RFQ</a></p>
<p><b>LA01M032S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 7127 pcs  <a href="#">RFQ</a></p>	<p><b>LA01P170S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 4602 pcs  <a href="#">RFQ</a></p>
<p><b>LA01P085S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 7438 pcs  <a href="#">RFQ</a></p>	<p><b>LA02P085S03</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 6260 pcs  <a href="#">RFQ</a></p>
<p><b>LA01M035S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 8381 pcs  <a href="#">RFQ</a></p>	<p><b>LA01M021S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 8400 pcs  <a href="#">RFQ</a></p>
<p><b>LA01P046S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 6605 pcs  <a href="#">RFQ</a></p>	<p><b>LA01P035S05</b>                  Manufacturers: Tamura                  Description: SENSOR                  Ao amin'ny staoky: 7069 pcs  <a href="#">RFQ</a></p>